

## **Reference Area Photographs**

**Inspection Conducted on August 20, 2015**

**Linn Energy**

**Old Mountain I02 696 Pad**

**Location ID #335617**

**Pit Facility IDs # 291074 and 415484**

## Linn Energy - Old Mountain I02 696 Pad



Signs need to be located at the entrance of the pad. Tanks with lined secondary containment.



Signs in place. Tubing must be removed if not to be used (housekeeping).

## Linn Energy - Old Mountain I02 696 Pad



Wellheads area protected with fence. Tubing and pipeline must be removed from Site if not to be used (Housekeeping).



South area of the pad (looking east) reclaimed. Pit ID #415484 has been backfilled, leveled and reseeded.

Note: Pit ID #291074 has also been backfilled. There are no more pits on site.

## Linn Energy - Old Mountain I02 696 Pad



Bermed stockpile of impacted material. According to Linn representative, Derek Johnson, this material comes from the pit recently closed and is being treated to reduce HC concentrations.



Close-up of stockpile (treatment cell) located on the southeast corner of the pad.