



Photo 1. View of rills approximately 12 inches wide and 10 inches deep within northern portion of project area.



Photo 2. View of eastern portion of project area from northeastern corner facing southward. Smooth brome (*Bromus inermis*) is growing in the foreground.





Photo 3. View from northern edge of project area facing center.



Photo 4. View of western portion of project area from northwestern corner facing southward.