

GLADE\* CHRIS OIL & GAS LLC -  
10378

MANHATTAN FEDERAL #1A

05-103-07875

9/23/2015

by Kyle P Granahan



Stained soil at wellhead – initial inspection



Stained soil at wellhead – follow up inspection



Stained soil at wellhead – 2<sup>nd</sup> follow up



Incomplete battery sign – initial inspection



Incomplete battery sign – follow up inspection



Incomplete battery sign – 2<sup>nd</sup> follow up



Empty drum – initial inspection



Empty drum – follow up inspection



Empty drum – 2<sup>nd</sup> follow up



Tank labels missing – initial inspection



Tank labels missing – follow up inspection



Tank labels missing – 2<sup>nd</sup> follow up insp