



photo 1: Facing southwest at the intersection of the Jawbreaker 12-29 and Cool Whip 22-29 locations along the access road where the produced water leak occurred.



photo 2: North side of the access road where produced water leak occurred.

Lat/Long: 37.32264,-104.70107



photo 3: Facing northeast along the access road where produced water leak occurred.



photo 4: Facing southwest along the access road where produced water had flowed along the side of the road.



photo 5: Approximately 400 ft. northeast of where the leak occurred. Soils changed from wet to completely dry. Point of where water flow appeared to stop. Lat/Long: 37.32372,-104.70087.



photo 6: Facing southwest past the above photo (5) point. There was no indication water had flowed recently and soils were dry.