

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
10/13/2015

Document Number:
675202133

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>334384</u>	<u>334384</u>	<u>CONKLIN, CURTIS</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100322</u>
Name of Operator:	<u>NOBLE ENERGY INC</u>
Address:	<u>1625 BROADWAY STE 2200</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Pavelka, Linda	(303) 228-4060	lpavelka@nobleenergyinc.com	Regulatory Analyst

Compliance Summary:

Qtr	Qtr	Sec	Twp	Range
SENW		34	7S	95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/26/2015	675201372			SATISFACTORY			No
03/26/2015	675201373			SATISFACTORY			No
09/23/2014	675200585			ACTION REQUIRED			No
07/12/2013	663801256			SATISFACTORY			No
07/12/2013	663801257			SATISFACTORY	I		No

Inspector Comment:

NO evidence of wells on location. This inspection is to pass Fianl Reclamation for AL wells only.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
298144	WELL	AL	08/28/2013	LO	045-17081	BATTLEMENT MESA 34 -22A (34F)	AL	<input checked="" type="checkbox"/>
298352	WELL	AL	11/22/2013	LO	045-17153	BATTLEMENT MESA 34 -32A (34Fpad)	AL	<input checked="" type="checkbox"/>
298353	WELL	AL	12/04/2012	LO	045-17154	Battlement Mesa 34-32B	AL	<input checked="" type="checkbox"/>
298354	WELL	AL	11/22/2013	LO	045-17155	BATTLEMENT MESA 34 -32C (34F)	AL	<input checked="" type="checkbox"/>
298355	WELL	PR	04/30/2013	GW	045-17156	BATTLEMENT MESA 34 -32D	PR	<input type="checkbox"/>
298356	WELL	PR	04/26/2010	GW	045-17157	BATTLEMENT MESA 34 -31A	PR	<input type="checkbox"/>
298357	WELL	PR	07/29/2013	GW	045-17158	BATTLEMENT MESA 34 -31B	PR	<input type="checkbox"/>

298358	WELL	PR	11/26/2012	GW	045-17159	BATTLEMENT MESA 34 -31C	PR	<input type="checkbox"/>
298359	WELL	AL	02/01/2015	LO	045-17160	BATTLEMENT MESA 34 -31D (34F)	AL	<input checked="" type="checkbox"/>
298360	WELL	PR	09/01/2014	GW	045-17161	BATTLEMENT MESA 34 -23A	PR	<input type="checkbox"/>
298361	WELL	PR	12/29/2009	GW	045-17162	BATTLEMENT MESA 34 -22B	PR	<input type="checkbox"/>
298362	WELL	PR	12/15/2009	GW	045-17163	BATTLEMENT MESA 34 -22C	PR	<input type="checkbox"/>
298363	WELL	PR	12/29/2009	GW	045-17164	BATTLEMENT MESA 34 -22D	PR	<input type="checkbox"/>
298364	WELL	AL	11/22/2013	LO	045-17165	BATTLEMENT MESA 34 -21D (34F)	AL	<input checked="" type="checkbox"/>
298548	WELL	PR	03/08/2012	GW	045-17152	BATTLEMENT MESA 34 -33A	PR	<input type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 334384

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 298144 Type: WELL API Number: 045-17081 Status: AL Insp. Status: AL

Facility ID: 298352 Type: WELL API Number: 045-17153 Status: AL Insp. Status: AL

Facility ID: 298353 Type: WELL API Number: 045-17154 Status: AL Insp. Status: AL

Facility ID: 298354 Type: WELL API Number: 045-17155 Status: AL Insp. Status: AL

Facility ID: 298359 Type: WELL API Number: 045-17160 Status: AL Insp. Status: AL

Facility ID: 298364 Type: WELL API Number: 045-17165 Status: AL Insp. Status: AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation Pass

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT