



Photo 1. View of tipped sign at the entrance to the project area.



Photo 2. View of stormwater erosion in the eastern portion of the project area. Erosional channels are formed (approximately 12 inches deep and 24 inches wide) and appear to be carrying sediment outside of the project area (in background).





Photo 3. Another view of stormwater erosion in the eastern portion of the project area. Erosional channels are flowing beneath and through project facilities.



Photo 4. View of northern portion of project area from northeastern corner facing westward. Dried weeds such as annual sunflower (*Helianthus annuus*) and Russian thistle (*Salsola tragus*) are growing here.





Photo 5. View southern portion of project area where Russian thistle and kochia (*Kochia scoparia*) debris is present.