



photo 1: Facing south towards the access road off of the main county road.



photo 2: Facing south along the access road towards the location.



photo 3: Facing south along the access road towards the location.



photo 4: North side of the location facing south.



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: Weed growth debris (Russian thistle) throughout the location.



photo 10: Photo of ground cover.



photo 11: West side of the location facing south. Perimeter fence is maintained.



photo 12: Surrounding vegetation growth.