

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

10/14/2015

Document Number:

675202140

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334071	334071	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Compliance Summary:QtrQtr: NWSW Sec: 28 Twp: 7S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/26/2015	675201376			SATISFACTORY			No
03/26/2015	675201375			SATISFACTORY			No
07/14/2014	675100215			ACTION REQUIRED			No

Inspector Comment:

No evidence of wells on location. This inspection is to pass Final Reclamation for AL wells only.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
67350	LEASE	PR	05/15/1997		-	BOULDER BANK 3-7	PR
260555	WELL	PR	05/17/2012	GW	045-07867	S. PARACHUTE FEDERAL 28-31	PR
260626	WELL	AL	06/05/2003	LO	045-07882	S. PARACHUTE FEDERAL 29-44	AL
278100	WELL	PR	05/10/2012	GW	045-10838	FEDERAL 29-16 (PL28)	PR
278101	WELL	AL	04/13/2010	LO	045-10837	FEDERAL 28-13 (PL28)	AL
278374	WELL	PR	05/17/2012	GW	045-10873	FEDERAL 28-6 (PL28)	PR
278375	WELL	PR	05/24/2012	GW	045-10874	FEDERAL 28-14 (PL28)	PR
420779	WELL	PR	05/08/2012	GW	045-20214	Federal 28-6BB (PL28)	PR
420780	WELL	PR	06/07/2012	GW	045-20215	Federal 28-5 (PL28)	PR

Inspector Name: CONKLIN, CURTIS

420790	WELL	PR	05/09/2012	GW	045-20225	Federal 28-12BB (PL28)	PR	
420794	WELL	PR	05/04/2012	GW	045-20229	Federal 28-13 (PL28)	PR	
420798	WELL	PR	06/07/2012	GW	045-20233	Federal 28-11 (PL28)	PR	
420807	WELL	PR	05/18/2012	GW	045-20234	Federal 29-9 (PL28)	PR	
420808	WELL	PR	06/07/2012	GW	045-20235	Federal 28-11BB (PL28)	PR	
420962	WELL	PR	05/28/2012	GW	045-20262	Federal 28-13BB (PL28)	PR	

Equipment:

Location Inventory

Special Purpose Pits:	<u>1</u>	Drilling Pits:	<u> </u>	Wells:	<u>12</u>	Production Pits:	<u> </u>
Condensate Tanks:	<u>4</u>	Water Tanks:	<u> </u>	Separators:	<u>12</u>	Electric Motors:	<u> </u>
Gas or Diesel Mortors:	<u> </u>	Cavity Pumps:	<u> </u>	LACT Unit:	<u> </u>	Pump Jacks:	<u> </u>
Electric Generators:	<u> </u>	Gas Pipeline:	<u> </u>	Oil Pipeline:	<u> </u>	Water Pipeline:	<u> </u>
Gas Compressors:	<u> </u>	VOC Combustor:	<u> </u>	Oil Tanks:	<u> </u>	Dehydrator Units:	<u> </u>
Multi-Well Pits:	<u> </u>	Pigging Station:	<u> </u>	Flare:	<u> </u>	Fuel Tanks:	<u> </u>

Location

Emergency Contact Number (S/A/V):

Corrective Date:

Comment:

Corrective Action:

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 334071

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 260626 Type: WELL API Number: 045-07882 Status: AL Insp. Status: AL

Facility ID: 278101 Type: WELL API Number: 045-10837 Status: AL Insp. Status: AL

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: CONKLIN, CURTIS

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: CONKLIN, CURTIS

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started:

Date Final Reclamation Completed:

Final Land Use: RANGELAND

Reminder:

Comment:

Well plugged

Pit mouse/rat holes, cellars backfilled

Debris removed

No disturbance /Location never built

Access Roads Regraded

Contoured

Culverts removed

Gravel removed

Location and associated production facilities reclaimed

Locations, facilities, roads, recontoured

Compaction alleviation

Dust and erosion control

Non cropland: Revegetated 80%

Cropland: perennial forage

Weeds present

Subsidence

Comment:

Corrective Action:

Date

Overall Final Reclamation Pass

Well Release on Active Location ☐

Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

S/A/V:

Corrective Date:

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT