

CEMENT JOB REPORT



CUSTOMER CARRIZO OIL & GAS INC XML			DATE 09-JAN-14		F.R. # 10011037142		SERV. SUPV. STEVEN S ISCHE						
LEASE & WELL NAME BRINGELSON RANCH 5-20-9-58 - API 05123385830			LOCATION 20-9N-58W			COUNTY-PARISH-BLOCK Weld Colorado							
DISTRICT Brighton			DRILLING CONTRACTOR RIG # Xtreme Coil #19			TYPE OF JOB Surface							
SIZE & TYPE OF PLUGS		LIST-CSG-HARDWARE		MECHANICAL BARRIERS		MD	TVD	HANGER TYPES	MD	TVD			
Cement Plug, Rubber, Top 9-5/8 in		Float Shoe 9-5/8 - 8rd		NONE		0	0	NONE	0	0			
		Float Collar, Ball Valve, 9-5/8 - 8rd											
		Centralizer, Positive, 9-5/8 in											
		Cement Basket, Hinged, 9-5/8 in											
MATERIALS FURNISHED BY BJ				LAB REPORT NO.		PHYSICAL SLURRY PROPERTIES							
						SACKS OF CEMENT	SLURRY WGT PPG	SLURRY YLD FT³	WATER GPS	PUMP TIME HR:MIN	Bbl SLURRY	Bbl MIX WATER	
Fresh Water + 2 lbs Red Dye				N/A		0	8.34	0	0	00:00	20		
Type III Cmt + adds				N/A		146	14.5	1.41	6.82	01:57	34	22.02	
Premium Lite Cmt + adds				N/A		399	13	1.81	9.46	04:00	125	87.14	
Fresh Water				N/A		0	8.34	0	0	00:00	109		
Available Mix Water 400 Bbl.				Available Displ. Fluid 266 Bbl.		TOTAL				288		109.17	
HOLE			TBG-CSG-D.P.					COLLAR DEPTHS					
SIZE	% EXCESS	DEPTH	ID	OD	WGT.	TYPE	MD	TVD	GRADE	SHOE	FLOAT	STAGE	
12.25	100	1465	8.921	9.625	36	CSG	1450	1450	J-55	1450	1402	0	
LAST CASING			PKR-CMT RET-BR PL-LINER			PERF. DEPTH			TOP CONN		WELL FLUID		
ID	OD	WGT	TYPE	MD	TVD	BRAND & TYPE	DEPTH	TOP	BTM	SIZE	THREAD	TYPE	WGT.
15.	16	65	CSG	70	70	NO PACKER	0	0	0	9.625	8RD	WATER BASED	8.6
DISPL. VOLUME		DISPL. FLUID		CAL. PSI	CAL. MAX PSI	OP. MAX	MAX TBG PSI		MAX CSG PSI		MIX WATER		
VOLUME	UOM	TYPE	WGT.	BUMP PLUG	TO REV.	SQ. PSI	RATED	Operator	RATED	Operator			
109	BBLs	Fresh Water	8.34	385	0	0	0	0	2816	1600	RIG		
Circulation Prior to Job													
Circulated Well: Rig <input checked="" type="checkbox"/> BJ <input type="checkbox"/>						Circulation Time: 1			Circulation Rate: 4 BPM				
Mud Density In: 8.6 LBS/GAL Mud Density Out: 8.6 LBS/GAL						PV & YP Mud In: 0			PV & YP Mud Out: 0				
Gas Present: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/> Units:						Solids Present at End of Circulation: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/>							
Displacement And Mud Removal													
Displaced By: Rig <input type="checkbox"/> BJ <input checked="" type="checkbox"/>						Amount Bled Back After Job: 1 BBLs							
Returns During Job: <input type="checkbox"/> NONE <input type="checkbox"/> PARTIAL <input checked="" type="checkbox"/> FULL						Method Used to Verify Returns: VISUAL							
Cement Returns at Surface: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO						Were Returns Planned at Surface: <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES							
Pipe Movement: <input type="checkbox"/> ROTATION <input type="checkbox"/> RECIPROCATION <input checked="" type="checkbox"/> NONE <input type="checkbox"/> UNABLE DUE TO STUCK PIPE													
Centralizers: <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES						Quantity: 15			Type: <input type="checkbox"/> BOW <input type="checkbox"/> RIGID				
Job Pumped Through: <input type="checkbox"/> CHOKE MANIFOLD <input type="checkbox"/> SQUEEZE MANIFOLD <input checked="" type="checkbox"/> MANIFOLD <input type="checkbox"/> NO MANIFOLD													
Plugs													
Number of Attempts by BJ: 0 Competition: 0						Wiper Balls Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES Quantity:							
Plug Catcher Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES						Parabow Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES							
Was There a Bottom: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES						Top of Plug: 0 FT			Bottom of Plug: 0 FT				
Squeezes (Update Original Treatment Report for Primary Job)													
BLOCK SQUEEZE <input type="checkbox"/> SHOE SQUEEZE <input type="checkbox"/> TOP OF LINER SQUEEZE <input type="checkbox"/> PLANNED <input type="checkbox"/> UNPLANNED <input type="checkbox"/>													
Liner Packer: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES						Bond Log: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES			PSI Applied: 0 Fluid Weight: 0 LBS/GAL				
Casing Test (Update Original Treatment Report for Primary Job)													
Casing Test Pressure: 1476 PSI With 8.34 LBS/GAL Mud						Time Held: 00 Hours 15 Minutes							
EXPLANATION: TROUBLE SETTING TOOL, RUNNING CSG, ETC. PRIOR TO CEMENTING: NONE													

CEMENT JOB REPORT



Shoe Test (Update Original Treatment Report for Primary Job)

Depth Drilled out of Shoe: 0 FT Target EMW: 0 LBS/GAL Actual EMW: 0 LBS/GAL
 Number of Times Tests Conducted: 0 Mud Weight When Test was Conducted: 0 LBS/GAL

Problems Before Job (I.E. Running Casing, Circulating Well, ETC)
 NONE

Problems During Job (I.E. Lost Returns, Equipment Failure, Bulk Delivery, Foaming, ETC)
 NONE

Problems After Job (I.E. Gas at Surface, Float Equipment Failed, ETC)
 NONE

PRESSURE/RATE DETAIL						EXPLANATION	
TIME HR:MIN.	PRESSURE - PSI		RATE BPM	Bbl. FLUID PUMPED	FLUID TYPE	SAFETY MEETING: BJ CREW <input checked="" type="checkbox"/> CO. REP. <input checked="" type="checkbox"/>	
	PIPE	ANNULUS				TEST LINES	3434 PSI
						CIRCULATING WELL - RIG	<input checked="" type="checkbox"/> BJ <input type="checkbox"/>
16:30	0	0	0	0	N/A	LEAVE YARD	
18:45	0	0	0	0	N/A	ARRIVE ON LOCATION	
20:00	0	0	0	0	N/A	SPOT TRUCKS AND PRE RIG UP SAFTY MEETING	
23:20	0	0	0	0	N/A	SAFTY MEETING WITH CREW	
00:13	140	0	2	2	H2O	LOAD LINES	
00:16	3434	0	0	0	H2O	PRESSURE TEST	
00:24	320	0	4.8	10	H2O	FRESH WATER SPACER	
00:27	289	0	4.8	10	H2O	DYE WATER SPACER	
00:39	253	0	3.7	125	CEMENT	BATCH UP, WHEIGH AND SEND 13# LEAD	
01:15	249	0	3.7	34	CEMENT	14.5# TAIL	
01:30	0	0	0	0	N/A	DROP PLUG	
01:33	567	0	4.7	80	H2O	DISPLACEMENT	
01:56	432	0	2	20	H2O	RATE CHANGE	
02:03	470	0	1	9	H2O	RATE CHANGE	
02:18	1018	0	0	0	H2O	BUMP PLUG	
02:20	0	0	0	0	N/A	TEST FLOATS	
02:25	1476	0	0	0	H2O	START CASING TEST	
02:25	1076	0	0	0	N/A	END CASING TEST (FLANGE LEAKING IN CELLAR)	
02:45	0	0	0	0	N/A	RIG DOWN SAFTY MEETING	
03:45	0	0	0	0	N/A	LEAVE LOCATION	

BUMPED PLUG	PSI TO BUMP PLUG	TEST FLOAT EQUIP.	BBL.CMT RETURNS/ REVERSED	TOTAL BBL. PUMPED	PSI LEFT ON CSG	SPOT TOP OUT CEMENT	Service Supervisor Signature:
<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	1018	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	59	290	0	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	