



Photo#1: Looking across Location from NE entrance.



Photo#2: View SW along East Berm .

October 19, 2015

Location # 335550



Photo#3: View along South Berm looking over interim reclamation area. Large areas of senesced Kochia, at stage to break and tumble.



Photo#4: View along North Berm, looking East at interim reclamation area.

October 19, 2015

Location # 335550



Photo#5: Matured Wheat in interim reclamation area.

October 19, 2015

Location # 335550



Photo#6: Close up of ground, soil conditions in areas of Kochia establishment.