

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

10/26/2015

Document Number:

681900094

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	434242	434248	HELGELAND, GARY	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
J, D		cogcc.djinspections@encana.com	D J Basin

**Compliance Summary:**QtrQtr: NESW Sec: 32 Twp: 2N Range: 68W**Inspector Comment:**Surface casings set and bredenheads plumed to surface. Wells not completed.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
434241	WELL	DG	01/11/2015	LO	123-38047	File 3E-32H K268	DG	<input checked="" type="checkbox"/>
434242	WELL	DG	01/09/2015	LO	123-38048	File 3G-32H K268	DG	<input checked="" type="checkbox"/>
434243	WELL	DG	01/12/2015	LO	123-38049	File 3B-32H K268	DG	<input checked="" type="checkbox"/>
434244	WELL	DG	01/01/2015	LO	123-38050	File 3H-32H K268	DG	<input checked="" type="checkbox"/>
434245	WELL	DG	01/10/2015	LO	123-38051	File 3F-32H K268	DG	<input checked="" type="checkbox"/>
434246	WELL	DG	01/11/2015	LO	123-38052	File 3D-32H K268	DG	<input checked="" type="checkbox"/>
434247	WELL	DG	01/12/2015	LO	123-38053	File 3C-32H K268	DG	<input checked="" type="checkbox"/>
434249	WELL	DG	01/01/2015	LO	123-38054	File 3A-32H K268	DG	<input checked="" type="checkbox"/>
434277	WELL	DG	02/27/2015	LO	123-38072	File 3I-32H K268	DG	<input checked="" type="checkbox"/>
434280	WELL	DG	01/01/2015	LO	123-38075	File 3K-32H K268	DG	<input checked="" type="checkbox"/>
434282	WELL	DG	01/06/2015	LO	123-38077	File 3O-32H K268	DG	<input checked="" type="checkbox"/>
434283	WELL	DG	01/06/2015	LO	123-38078	File 3P-32H K268	DG	<input checked="" type="checkbox"/>

Inspector Name: HELGELAND, GARY

434284	WELL	DG	01/01/2015	LO	123-38079	File 3J-32H K268	DG	<input checked="" type="checkbox"/>
434285	WELL	DG	01/10/2015	LO	123-38080	File 3M-32H K268	DG	<input checked="" type="checkbox"/>
434287	WELL	DG	01/10/2015	LO	123-38082	File 3L-32H K268	DG	<input checked="" type="checkbox"/>
434289	WELL	DG	01/09/2015	LO	123-38083	File 3N-32H K268	DG	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>16</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>8</u>	Separators: <u>16</u>	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>24</u>	Oil Tanks: <u>28</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/A/V): \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Pipe and rod fencing		

**Venting:**

Yes/No	Comment

**Flaring:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 434242

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 434241 Type: WELL API Number: 123-38047 Status: DG Insp. Status: DG

**Well Drilling****Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Inspector Name: HELGELAND, GARY

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: bredenheads plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434242 Type: WELL API Number: 123-38048 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: bredenheads plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434243 Type: WELL API Number: 123-38049 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: bredenheads plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434244 Type: WELL API Number: 123-38050 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: bredenheads plumed to surface

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434245 Type: WELL API Number: 123-38051 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434246 Type: WELL API Number: 123-38052 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Inspector Name: HELGELAND, GARY

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434247 Type: WELL API Number: 123-38053 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434249 Type: WELL API Number: 123-38054 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434277 Type: WELL API Number: 123-38072 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434280 Type: WELL API Number: 123-38075 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434282 Type: WELL API Number: 123-38077 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Inspector Name: HELGELAND, GARY

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434283 Type: WELL API Number: 123-38078 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434284 Type: WELL API Number: 123-38079 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434285 Type: WELL API Number: 123-38080 Status: DG Insp. Status: DG



**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434287 Type: WELL API Number: 123-38082 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 434289 Type: WELL API Number: 123-38083 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Inspector Name: HELGELAND, GARY

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

Surface casings set and bredenheads plumed to surface. Wells not completed.

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: IRRIGATED

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

- 1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_ In Process \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IRRIGATED \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_

Y \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

