



Photo#1: Overview of Location, looking to NW



Photo#2: Overview of Location, looking to SE from end point of Access road.





Photo#3: Gully forming at NE edge of Location, running SW.



Photo#4: Termination of Gully , exposed undercut culvert at right.





Photo#5: View of North slope with sparse vegetation , Gully intersecting, Game Trail running through North to South.



Photo #6: Old Access Road into location