



Photo 1. View of dense kochia (*Kochia scoparia*; approximately 5 to 6 feet tall) growing on both sides of the access road from the well pad entrance facing southward.





Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.





Photo 3. View of northeastern portion of project area facing southward. Dense kochia is growing here.





Photo 4. View of northern portion of project area from northeastern corner facing westward. Dense kochia is also growing here.





Photo 5. View of Russian knapweed plants in the eastern portion of the project area.





Photo 6. View of stormwater erosion occurring in the eastern portion of the project area.





Photo 7. View of perennial stream that flows adjacent to the northern and eastern portions of the project area facing northeastward.