



**Photo 1.** Photo taken from southeast entrance, facing North. Note the Kochia (*Kochia sp.*) and Russian thistle (*Salsola sp.*) in the photo. This is weed debris and will break off and encroach upon adjacent lands. When interim reclamation starts, this area shall be reclaimed and minimized where production or facilities are no longer necessary.



**Photo 2.** Photo taken from southeast entrance, facing West.





**Photo 3.** Photo taken from northeast location, facing North.



**Photo 4.** Photo taken from northeast location, facing West. Road base soil piles need to be removed if no longer needed.





**Photo 5.** Photo taken from northwest location, facing East.



**Photo 6.** Photo taken from northwest location, facing South. Note the Kochia (*Kochia sp.*), Russian thistle (*Salsola sp.*) and Canada thistle (*Cirsium arvense*) in the photo. Weed maintenance is needed to prevent invasion of undesirable species and noxious weeds upon adjacent lands.





**Photo 7.** Photo taken from southwest location, facing East. Note the Kochia (*Kochia sp.*) and Russian thistle (*Salsola sp.*) in the photo. This is weed debris and will break off and encroach upon adjacent lands.



**Photo 8.** Photo taken from southwest location, facing North. Note the Kochia (*Kochia sp.*), Russian thistle (*Salsola sp.*) and Canada thistle (*Cirsium arvense*) in the photo. Weed maintenance is needed to prevent invasion of undesirable species and noxious weeds upon adjacent lands.





**Photo 9.** Photo taken from southwest location, facing East. Note the Canada thistle (*Cirsium arvense*) in the photo. Weed maintenance is needed to prevent invasion of undesirable species and noxious weeds upon adjacent lands.



**Photo 10.** The perimeter, in yellow, illustrates the disturbance boundary as of 10/29/15. Total disturbance equals 5.33 acres.