

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400932127

Date Received:

11/06/2015

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

443488

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>EXTRACTION OIL & GAS LLC</u>	Operator No: <u>10459</u>	Phone Numbers Phone: <u>()</u> Mobile: <u>(720) 481-2372</u> Email: <u>jcarlisle@extractionog.com</u>
Address: <u>370 17TH STREET SUITE 5300</u>		
City: <u>DENVER</u>	State: <u>CO</u> Zip: <u>80202</u>	
Contact Person: <u>Josh Carlisle</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400911039

Initial Report Date: 10/05/2015 Date of Discovery: 10/01/2015 Spill Type: Historical Release

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SESE SEC 25 TWP 5N RNG 69W MERIDIAN 6Latitude: 40.366521 Longitude: -105.059362Municipality (if within municipal boundaries): _____ County: LARIMER

Reference Location:

Facility Type: TANK BATTERY ☐ Facility/Location ID No _____☒ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): UnknownEstimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: CROP LAND Other(Specify): _____Weather Condition: DrySurface Owner: FEE Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During removal of a separator from the Skaer #3 tanks battery stained soils were observed. It is unknown the cause of the duration of the release. The separator has been removed from the location. A form 27 will be filed shortly to indicate the project plans and sampling results.

List Agencies and Other Parties Notified:

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Josh Carlisle

Title: Environmental Supervisor Date: 11/06/2015 Email: jcarlisle@extractionog.com

COA Type

Description

	Elevated SAR in the west wall of the excavation is likely related to the former produced water pit which was closed by Remediation Project 5874. The elevated SAR is below the root zone, however the Operator is responsible for successful reclamation of the site. If the elevated SAR prevents successful reclamation of the site, then additional soil remediation may be required.
--	--

Attachment Check List

Att Doc Num

Name

400932127	FORM 19 SUBMITTED
400932128	OTHER
400932129	ANALYTICAL RESULTS
400932133	SITE MAP

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)