



Photo 1: Photo taken from north end of location, facing south. Note inadequate perennial vegetative growth.



Photo 2: Photo taken from eastern end of location, facing west. Note inadequate perennial vegetative growth. .



Photo 3: Photo taken from southern end of location, facing north.



Photo 4: Photo taken from western end of location, facing east.