



#### NOTES / COMMENTS:

Bottom & Trench 01 were collected as water samples

SS 01, SS 02, SS 03, & SS 04 were collected as soil samples

DISCLAIMER: This representation and the Geographic Information System (GIS) used to create it are designed as a source of reference and not intended to replace official records and/or legal surveys. HCSL assumes no responsibility for any risks, dangers, or liabilities that may result from its use and makes no guarantee as to the quality or accuracy of the underlying data.



#### Sample Location Map

**Boies Ranch 27-A**

39.851732 -108.372788  
Section 27, Township 2 South, Range 98 West

● Sample Location

▨ Excavated Area

▨ Trench



**HRL COMPLIANCE SOLUTIONS, INC.**  
Environmental Consultants

Author: E. Fought

Revision: 1

Date: 7/27/2015