

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400936265

Date Received:

11/13/2015

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

443874

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	<b>Phone Numbers</b>
Address: <u>1625 BROADWAY STE 2200</u>		Phone: <u>(970) 3045329</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Jacob Evans</u>		Mobile: <u>( )</u>
		Email: <u>jacob.evans@nblenergy.com</u>

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400930328

Initial Report Date: 11/04/2015 Date of Discovery: 11/04/2015 Spill Type: Historical Release

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR SENW SEC 34 TWP 5N RNG 65W MERIDIAN 6Latitude: 40.358563 Longitude: -104.649408Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

#### Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 322916☐ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): >=1 and <5Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

#### Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: Clear 50Surface Owner: FEE

Other(Specify): \_\_\_\_\_

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During dismantlement of the facility, impacts were discovered by the oil and produced water lines running from the tank battery to the separator. Facility is not producing and is shut in. Remediation analysis is underway.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
11/4/2015	COGCC	Rick Allison	-	Emailed 24hr notice
11/4/2015	Weld County	Gracie Marquez	-	Emailed 24hr notice
11/4/2015	Noble Land	Luke Musgrave	-	Notified Landowner

**SPILL/RELEASE DETAIL REPORTS**

#1	Supplemental Report Date: 11/13/2015		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL			<input checked="" type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply) ☒ Soil ☒ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): \_\_\_\_\_ Width of Impact (feet): \_\_\_\_\_

Depth of Impact (feet BGS): \_\_\_\_\_ Depth of Impact (inches BGS): \_\_\_\_\_

How was extent determined?

The extent of impacts will be determined through a site assessment. Groundwater and soil quality will be delineated at the Bacon 3 facility.

Soil/Geology Description:

well graded sand

Depth to Groundwater (feet BGS) 3 Number Water Wells within 1/2 mile radius: 22

If less than 1 mile, distance in feet to nearest	Water Well <u>1416</u>	None <input type="checkbox"/>	Surface Water <u>55</u>	None <input type="checkbox"/>
	Wetlands _____	None <input checked="" type="checkbox"/>	Springs _____	None <input checked="" type="checkbox"/>
	Livestock <u>1500</u>	None <input type="checkbox"/>	Occupied Building <u>1538</u>	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

no additional spill details

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 11/13/2015

Cause of Spill (Check all that apply) ☐ Human Error ☒ Equipment Failure ☐ Historical-Unknown  
☐ Other (specify) \_\_\_\_\_

Describe Incident & Root Cause (include specific equipment and point of failure)

The produced water and oil lines were leaking which ran from the separator to the tanks

Describe measures taken to prevent the problem(s) from reoccurring:

The location will be dismantled and moved to the Boulter 17-34 location.

Volume of Soil Excavated (cubic yards): \_\_\_\_\_

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment  
☐ Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

## OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Jacob Evans

Title: Environmental Specialist Date: 11/13/2015 Email: jacob.evans@nblenergy.com

## Attachment Check List

Att Doc Num	Name
-------------	------

--	--

Total Attach: 0 Files

## General Comments

User Group	Comment	Comment Date
------------	---------	--------------

--	--	--

Total: 0 comment(s)