

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
11/27/2015

Document Number:  
666801678

Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>292140</u>	<u>335007</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>10456</u>
Name of Operator:	<u>CAERUS PICEANCE LLC</u>
Address:	<u>600 17TH STREET #1600N</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
McKee, Michael	720-880-6322 Direct	mmckee@caerusoilandgas.com	EHS (all Inspections)
Elsener, Garrett		garrett@caerusoilandgas.com	

**Compliance Summary:**

QtrQtr: NWSW Sec: 5 Twp: 7S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/14/2011	200298470	PR	PR	SATISFACTORY			Yes
12/19/2008	200200980	PR	PR	SATISFACTORY			No

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
292140	WELL	PR	08/30/2008	GW	045-14605	SAVAGE 5-13A	PR	<input checked="" type="checkbox"/>
292737	WELL	PR	09/14/2009	GW	045-14766	SAVAGE 5-13B	PR	<input checked="" type="checkbox"/>
292738	WELL	PR	01/08/2009	GW	045-14765	SAVAGE 5-14D	PR	<input checked="" type="checkbox"/>
292739	WELL	PR	10/08/2008	GW	045-14764	SAVAGE 5-14C	PR	<input checked="" type="checkbox"/>
292740	WELL	PR	10/08/2008	GW	045-14763	SAVAGE 5-14B	PR	<input checked="" type="checkbox"/>
292741	WELL	PR	10/08/2008	GW	045-14762	SAVAGE 5-14A	PR	<input checked="" type="checkbox"/>
292742	WELL	PR	08/12/2011	GW	045-14761	SAVAGE 5-13D	PR	<input checked="" type="checkbox"/>
292743	WELL	PR	11/19/2009	GW	045-14760	SAVAGE 5-13C	PR	<input checked="" type="checkbox"/>
292829	WELL	PR	11/19/2009	GW	045-14795	SAVAGE 5-23A	PR	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

292830	WELL	PR	08/26/2009	GW	045-14794	SAVAGE 5-23B	PR	✗
292831	WELL	PR	01/07/2011	GW	045-14793	SAVAGE 5-23C	PR	✗
292832	WELL	PR	11/19/2009	GW	045-14792	SAVAGE 5-23-D	PR	✗
292835	WELL	PR	10/08/2008	GW	045-14791	SAVAGE 5-24A	PR	✗
292836	WELL	PR	10/08/2008	GW	045-14789	SAVAGE 5-24C	PR	✗
292837	WELL	PR	01/08/2009	GW	045-14788	SAVAGE 5-24D	PR	✗
292846	WELL	PR	10/08/2008	GW	045-14790	SAVAGE 5-24B	PR	✗

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	AIRS ID 045-1685-001		

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Pig Station	1	SATISFACTORY			
Plunger Lift	16	SATISFACTORY			
Horizontal Heated Separator	16	SATISFACTORY			
Emission Control Device	1	SATISFACTORY			

<b>Venting:</b>	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 292140

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 292140 Type: WELL API Number: 045-14605 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger Lift**

Facility ID: 292737 Type: WELL API Number: 045-14766 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger Lift**

Facility ID: 292738	Type: WELL	API Number: 045-14765	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292739	Type: WELL	API Number: 045-14764	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292740	Type: WELL	API Number: 045-14763	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292741	Type: WELL	API Number: 045-14762	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292742	Type: WELL	API Number: 045-14761	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292743	Type: WELL	API Number: 045-14760	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292829	Type: WELL	API Number: 045-14795	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292830	Type: WELL	API Number: 045-14794	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292831	Type: WELL	API Number: 045-14793	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292832	Type: WELL	API Number: 045-14792	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292835	Type: WELL	API Number: 045-14791	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger Lift</span>				
Facility ID: 292836	Type: WELL	API Number: 045-14789	Status: PR	Insp. Status: PR

**Producing Well**

Comment: Plunger Lift

Facility ID: 292837 Type: WELL API Number: 045-14788 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger Lift

Facility ID: 292846 Type: WELL API Number: 045-14790 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger Lift

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): Y

Comment: \_\_\_\_\_

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Compaction	Pass			
		Culverts	Pass			
Berms	Pass					

Inspector Name: Murray, Richard

S/A/V: SATISFACTOR  
Y

Corrective Date: \_\_\_\_\_

Comment: Snow covered location and access road

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT