



**Photo 1.** Photo taken from northwest corner, facing South. No noxious weed present and contoured back to agricultural field. Water pooling present along perimeter of well pad.



**Photo 2.** Photo taken from northwest corner, facing East. No noxious weed present and contoured back to agricultural field. Water pooling present along perimeter of well pad.



**Photo 3.** Photo taken from southwest corner, facing East. No noxious weed present and contoured back to agricultural field. Water pooling present along perimeter of well pad.



**Photo 4.** Photo taken from northwest corner, facing North. No noxious weed present and contoured back to agricultural field. Water pooling present along perimeter of well pad.



**Photo 5.** Photo taken from southeast corner, facing North. No noxious weed present and contoured back to agricultural field. Water pooling present along perimeter of well pad.



**Photo 6.** Photo taken from northeast corner, facing West. No noxious weed present and contoured back to agricultural field. Water pooling present along perimeter of well pad.