



**Photo 1.** Photo taken from center of well pad, facing North. Interim reclamation in process with less than 80 percent vegetative cover.



**Photo 2.** Photo taken from center of well pad, facing East. Interim reclamation in process with less than 80 percent vegetative cover.



**Photo 3.** Photo taken from center of well pad, facing South. Interim reclamation in process with less than 80 percent vegetative cover.



**Photo 4.** Photo taken from center of well pad, facing West. Interim reclamation in process with less than 80 percent vegetative cover.



**Photo 5.** Photo taken from center of well pad, facing straight down. Interim reclamation in process with less than 80 percent vegetative cover.



**Photo 6.** Photo taken from random reference area, facing North. Russian thistle dominates the reference area and adjacent lands.



**Photo 7.** Photo taken from random reference area, facing East. Russian thistle dominates the reference area and adjacent lands.



**Photo 8.** Photo taken from random reference area, facing South. Russian thistle dominates the reference area and adjacent lands.



**Photo 9.** Photo taken from random reference area, facing West. Russian thistle dominates the reference area and adjacent lands.



**Photo 10.** Photo taken from random reference area, facing straight down. Russian thistle dominates the reference area and adjacent lands.