



**Photo 1.** Photo taken from northern location, facing South. Location meets reclamation regulation standards. Final reclamation complete.



**Photo 2.** Photo taken from western location, facing East. Location meets reclamation regulation standards. Final reclamation complete.



**Photo 3.** Photo taken from southern location, facing North. Location meets reclamation regulation standards. Final reclamation complete.



**Photo 4.** Photo taken from eastern location, facing West. Location meets reclamation regulation standards. Final reclamation complete.



**Photo 5.** Photo taken from center of location, facing straight down. Location meets reclamation regulation standards. Final reclamation complete.



**Photo 6.** Reference area, facing South.



**Photo 7.** Reference area, facing East.



**Photo 8.** Reference area, facing North.



**Photo 9.** Reference area, facing West.



**Photo 10.** Reference area, facing straight down.