



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

1120 Lincoln Street, Suite 801
Denver, CO 80203

December 2, 2015

Michael A. Lozinski
11755 CR 15
Longmont, CO 80504

Dear Mr. Lozinski,

The Colorado Oil and Gas Conservation Commission (COGCC) received your complaint regarding noise originating from the southeast of your residence. Your complaint is documented in COGCC document number 200437869, which can be found on the "Complaints" page, off of our main website <http://cogcc.state.co.us/>. The COGCC investigated this complaint and documented the results in COGCC document number 200437879.

The following actions were taken to address your complaint:

- On 11/02/2015, COGCC Inspector Jeff Rikard arrived at the Vogl Geist location and conducted a sound survey; and
- Mr. Rikard documented this inspection and survey in Field Inspection Report # 674102725, which is attached to this letter.

During the inspection, noise levels outside of compliance with COGCC rules were not observed.

Therefore, the COGCC has determined that no violations occurred related to your complaint. Accordingly, the COGCC has closed the complaint and will not issue a notice of alleged violation (NOAV) related to this complaint.

If you have questions related to this investigation, please contact me.

Sincerely,

Megan Adamczyk, Complaint Specialist
303-894-2100 ext. 5145
dnr_cogcc.complaints@state.co.us



Inspector Name: Rickard, Jeff

FORM
INSP

Rev
05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

11/02/2015

Document Number:

674102725

Overall Inspection:

SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>
	433854	433854	Rickard, Jeff	2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100185

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED
☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.djinspections@encana.com	Group email
Adamczyk, Megan		megan.adamczyk@state.co.us	

Compliance Summary:

QtrQtr: SWNW Sec: 5 Twp: 2N Range: 67W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
433849	WELL	PR	12/02/2014	OW	123-37815	Vogl-McCoy 2B-5H-E267	PR	X
433850	WELL	PR	12/02/2014	OW	123-37816	VOGL-GEIST 2B-5H-E267	PR	X
433851	WELL	PR	01/09/2015	OW	123-37817	VOGL-GEIST 2A-5H-E267	PR	X
433852	WELL	PR	12/02/2014	OW	123-37818	VOGL-MCCOY 2C-5H-E267	PR	X
433853	WELL	PR	12/02/2014	OW	123-37819	Vogl-McCoy 2A-5H-E267	PR	X
433855	WELL	PR	12/02/2014	OW	123-37820	VOGL-MCCOY 2D-5H-E267	PR	X
433937	WELL	PR	12/02/2014	OW	123-37860	VOGL-GEIST 2C-5H-E267	PR	X
442867	TANK BATTERY	AC	01/09/2015		-	Vogl-Geist-McCoy 5H-E267	AC	
442868	TANK BATTERY	AC	01/09/2015		-	Vogl-Geist-McCoy 5H-E267	AC	

Equipment:

Location Inventory

Inspector Name: Rickard, Jeff

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>7</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>8</u>	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>7</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>13</u>	Oil Tanks: <u>18</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AV): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

<u>Spills:</u>				
Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

<u>Venting:</u>		
Yes/No	Comment	

<u>Flaring:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 433854

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	youngr	The tank battery shall be constructed using a liner.	07/15/2013

S/A/V: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/A/V: _____ Comment: _____

CA: _____ Date: _____

Stormwater:

Comment: _____

Staking:**On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 433849 Type: WELL API Number: 123-37815 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Complaint

Comment: Complaint DOC#200437869. Area resident filed a complaint about noise coming from location. Complainant stated the noise happened at random times and for random intervals. OGCC staff was on location on 11/2/15 and ran a sound survey. A scale was observed to be 37-40 db when no traffic was on CR15, OGCC staff talked to complainant and stated that the location was in compliance. OGCC staff informed the complainant that they could call inspector directly when the noise was happening next time it happened and OGCC staff will try to get to the location to measure the sound. 18A DOC#200437879.

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433850 Type: WELL API Number: 123-37816 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433851 Type: WELL API Number: 123-37817 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433852 Type: WELL API Number: 123-37818 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433853 Type: WELL API Number: 123-37819 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433855 Type: WELL API Number: 123-37820 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433937 Type: WELL API Number: 123-37860 Status: PR Insp. Status: PR

Producing WellComment: **PR****BradenHead**Comment: **Braden head is exposed at surface.**

CA: _____

CA Date: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Complaint:

Tracking Num	Category	Assigned To	Description	Incident Date
200415687	NOISE	Gomez, Jason	On 10-23-2014 I was contacted by email from complaint Mike Lozinski who resides at 11755 county road 15, Longmont Co. 80504. The complaint stated in his email that the noise coming from the location across the road from his residence was causing him to be a woken in the night from the noise coming from the site. In a later email sent on 10-23-2014 the complaint indicated the noise was "squelching noise every 5-10 seconds that lasted about 2-3 seconds."	10/27/2014
200409898	NOISE	Gomez, Jason	On 7-28-2014 I was notified of a complaint recived by the COGCC office in reference to a noise complaint coming from a location to the southeast of the complaints residence of 11755 county road 15, Longmont Co. 80504. The complaint Michael A. Lozinski indicated the noise coming from the location was causing his home to shake, he also indicated the noise was continous 24/7 which was affecting his ability to sleep at night.	07/28/2014

Emission Control Burner (ECB): **Y**

Comment: _____

Pilot: **ON** Wildlife Protection Devices (fired vessels): **YES****Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: **IRRIGATED**

Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Inspector Name: Rickard, Jeff

Corrective Action: Date

Overall Final Reclamation ☐ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

S/AV: SATISFACTOR
Y Corrective Date:

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674102726	Sound Survey	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3714563