

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400946719

Date Received:

12/03/2015

Spill report taken by:

Spencer, Stan

Spill/Release Point ID:

444175

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u>	Operator No: <u>100185</u>	Phone Numbers
Address: <u>370 17TH ST STE 1700</u>		Phone: <u>(970) 2852925</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202-5632</u>
Contact Person: <u>Matt Kasten</u>		Mobile: <u>(970) 9019007</u>
		Email: <u>matt.kasten@encana.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400945801

Initial Report Date: 12/02/2015 Date of Discovery: 12/01/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SENE SEC 8 TWP 4S RNG 97W MERIDIAN 6

Latitude: 39.718081 Longitude: -108.297152

Municipality (if within municipal boundaries): _____ County: RIO BLANCO

Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 316354

☐ No Existing Facility or Location ID No.

☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: Cold

Surface Owner: FEDERAL

Other(Specify): BLM

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The lease operator for the H08 well pad in Rio Blanco County had standing fluid in the lined secondary containment. The location was shut in and the fluid was removed. The fire tube on the tank had failed and released approximately 50 bbl into secondary containment. No fluid left secondary containment. The tank has been isolated and repairs are scheduled.

List Agencies and Other Parties Notified:

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 12/03/2015		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	50	65	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? YES Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☐ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 0 Width of Impact (feet): 0

Depth of Impact (feet BGS): 0 Depth of Impact (inches BGS): 0

How was extent determined?

The release did not travel beyond the lined secondary containment.

Soil/Geology Description:

Barcus channery loamy sand, 2 to 9 percent slopes

Depth to Groundwater (feet BGS) 30 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest

Water Well	<u> </u>	None <input checked="" type="checkbox"/>	Surface Water	<u>328</u>	None <input type="checkbox"/>
Wetlands	<u> </u>	None <input checked="" type="checkbox"/>	Springs	<u> </u>	None <input checked="" type="checkbox"/>
Livestock	<u> </u>	None <input checked="" type="checkbox"/>	Occupied Building	<u> </u>	None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

Release was contained and all free fluid was removed on same day as release. Vac truck removed 65 bbl of fluid; stormwater included with 50bbl of produced water.

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

Attn: Stan Spencer

H08 Tank Release
Form 19 Supplemental/Closure

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Matt Kasten

Title: Env. Consultant Date: 12/03/2015 Email: matt.kasten@encana.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

400946734	TOPOGRAPHIC MAP
-----------	-----------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)