



photo 1: Facing east off of the county road. A two track road is still evident which goes to the location.



photo 2: GPS indicating proximaty of the location..



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.



Photo 5: Center of the location facing south.



photo 6: Center of the location facing south.



photo 7: Weeds (kochia, russian thistle) are the predominate vegetation throughout the location.



photo 8: Weeds (kochia, russian thistle) are the predominate vegetation throughout the location.



photo 9: Barbed wire debris found at the north side of the location.



photo 10: Surrounding vegetation growth, reference area.



photo 10: 10/2015 aerial photo of the location.