

Mahalo #3, COGCC Field Inspection on 12/3/2015—Field Photos



Figure 1 - Well sign. COGCC attempted to contact operator via phone number provided on sign, which went to a recorded message. COGCC could not leave message for operator because the voice mailbox was full



Figure 2 – Unincorporated drilling mud NW of pad





Figure 3 – Unincorporated drilling mud NW of pad