


IMAGE COURTESY OF ESRI

**LEGEND**

- \* PHOTO
- ONSITE SAMPLE
- ▲ OFFSITE SAMPLE
- RECLAMATION AREA
- LONG TERM DISTURBANCE
- ACCESS ROAD



RECLAMATION AREA: 2.09 ACRES  
 LONG TERM DISTURBANCE AREA: 1.31 ACRES

RECLAMATION MONITORING MAP  
 NON-BLM LAND  
 MILLER PAD 6  
 GARFIELD COUNTY, COLORADO



**VANGUARD OPERATING, LLC**



**Onsite North**



**Onsite East**



**Onsite South**



**Onsite West**

Photos Taken: 08/07/2015

Miller Pad 6

**Site Photographs**



Offsite North



Offsite East



Offsite South



Offsite West

Photos Taken: 08/07/2015

Miller Pad 6

**Site Photographs**