

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/10/2015

Document Number:

674702173

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335594	335594	LONGWORTH, MIKE	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

**Compliance Summary:**QtrQtr: SENE Sec: 29 Twp: 5S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/03/2015	671000143			SATISFACTORY			No
12/31/2013	663902582			ACTION REQUIRED			No
12/31/2013	663902581			ACTION REQUIRED	F		No

**Inspector Comment:**


---

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
281254	WELL	PR	11/14/2006	GW	045-11414	N.PARACHUTE EF 16D H29A 595	PR	<input checked="" type="checkbox"/>
281255	WELL	PR	02/01/2014	GW	045-11415	N.PARACHUTE EF 15B H29A 595	PR	<input checked="" type="checkbox"/>
281256	WELL	PR	11/10/2005	GW	045-11416	N.PARACHUTE EF01B H29A 595	PR	<input checked="" type="checkbox"/>
281257	WELL	PR	11/24/2006	GW	045-11417	N.PARACHUTE EF16B H29A 595	PR	<input checked="" type="checkbox"/>
281258	WELL	PR	11/03/2006	GW	045-11418	N.PARACHUTE EF09B H29A 595	PR	<input checked="" type="checkbox"/>
281259	WELL	PR	11/08/2006	GW	045-11419	N. PARACHUTE EF01D H29A 595	PR	<input checked="" type="checkbox"/>
281260	WELL	PR	11/10/2005	GW	045-11420	N.PARACHUTE EF 15D H29A 59	PR	<input checked="" type="checkbox"/>
281261	WELL	PR	02/01/2014	GW	045-11421	N.PARACHUTE EF 10D H29A 595	PR	<input checked="" type="checkbox"/>
296524	WELL	AL	07/08/2011	LO	045-16054	N. PARACHUTE EF02A-29	AL	<input type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

296525	WELL	AL	09/16/2010	LO	045-16055	N. PARACHUTE EF02C-29	AL	
296526	WELL	AL	07/08/2011	LO	045-16056	N. PARACHUTE EF14B-20	AL	
296527	WELL	AL	07/08/2011	LO	045-16057	N. PARACHUTE EF14A-20	AL	
296528	WELL	PA	08/06/2014	GW	045-16058	N. PARACHUTE EF15D-20 H29A 5	PA	
296529	WELL	AL	07/08/2011	LO	045-16059	N. PARACHUTE EF14D-20	AL	
296530	WELL	PA	08/07/2014	LO	045-16060	N. PARACHUTE EF10C-20 H29A 5	PA	
296531	WELL	AL	07/08/2011	LO	045-16061	N. PARACHUTE EF14C-20 H29A	AL	
296532	WELL	PA	08/05/2014	GW	045-16062	N. PARACHUTE EF15B-20 H29A 5	PA	
296533	WELL	PA	08/08/2014	GW	045-16063	N. PARACHUTE EF16D-20 H29A 5	PA	
296534	WELL	PA	07/31/2014	GW	045-16064	N. PARACHUTE EF10A20 H29A 59	PA	
296535	WELL	PA	08/06/2014	GW	045-16065	N. PARACHUTE EF01B-29 H29A 5	PA	
433716	PIT	AC	07/25/2013		-	H29A 433716	AC	

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b><u>Signs/Marker:</u></b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: **800-791-7691**

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	<b>ACTION REQUIRED</b>	Unused/unneeded equipment on location.	Remove unused/unneeded equipment on location.	01/11/2016

**Spills:**

Inspector Name: LONGWORTH, MIKE

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	2	SATISFACTORY			
Plunger Lift	8	SATISFACTORY			
Gas Meter Run	8	SATISFACTORY	Gas lift		
Gas Meter Run	8	SATISFACTORY			

<b>Venting:</b>	
Yes/No	Comment
NO	

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335594

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 281254 Type: WELL API Number: 045-11414 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 281255 Type: WELL API Number: 045-11415 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 281256 Type: WELL API Number: 045-11416 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 281257 Type: WELL API Number: 045-11417 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 281258 Type: WELL API Number: 045-11418 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Facility ID: 281259 Type: WELL API Number: 045-11419 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 281260 Type: WELL API Number: 045-11420 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 281261 Type: WELL API Number: 045-11421 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

**Environmental****Spills/Releases:**

Type of Spill:  Description:  Estimated Spill Volume:

Comment:

Corrective Action:  Date:

Reportable:  GPS: Lat  Long

Proximity to Surface Water:  Depth to Ground Water:

**Water Well:**

Lat  Long

DWR Receipt Num:  Owner Name:  GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started:  Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? **Fail** CM **Unused/unneeded equipment on location.**  
 CA **Remove unused/unneeded equipment.** CA Date **01/11/2016**  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

#### Overall Interim Reclamation

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams	Pass			
				MHSP	Pass	
Gravel	Pass					
Compaction	Pass					
Berms	Pass					
		Ditches	Pass			
Seeding	Pass					
		Culverts	Pass			

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_  
Y \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674702174	Unused/unneeded equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3739028">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3739028</a>