

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/23/2015

Document Number:

675202344

Overall Inspection:

SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	442547	442549	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	10433
Name of Operator:	PICEANCE ENERGY LLC DBA LARAMIE ENERGY
Address:	1401 SEVENTEENTH STREET #1400
City:	DENVER
State:	CO
Zip:	80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Compliance Summary:

QtrQtr: NESW Sec: 28 Twp: 9S Range: 93W

Inspector Comment:

Drilling inspection

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
442546	WELL	DG	11/21/2015		077-10246	Piceance Fed 28-11E	DG	<input type="checkbox"/>
442547	WELL	DG	12/21/2015		077-10247	Piceance Fed 28-05E	DG	<input checked="" type="checkbox"/>
442548	WELL	DG	10/29/2015		077-10248	Piceance Fed 28-14E	DG	<input type="checkbox"/>
442550	WELL	DG	11/02/2015		077-10249	Piceance Fed 28-13E	DG	<input type="checkbox"/>
442551	WELL	DG	10/09/2015		077-10250	Piceance Fed 28-21E	DG	<input type="checkbox"/>
442553	WELL	XX	07/21/2015		077-10251	Piceance Fed 28-08E	XX	<input type="checkbox"/>
442555	WELL	DG	12/17/2015		077-10252	Piceance Fed 28-06E	DG	<input type="checkbox"/>
442556	WELL	DG	11/16/2015		077-10253	Piceance Fed 28-12E	DG	<input type="checkbox"/>
442558	WELL	DG	10/20/2015		077-10254	Piceance Fed 28-19E	DG	<input type="checkbox"/>
442559	WELL	DG	12/09/2015		077-10255	Piceance Fed 28-09E	DG	<input type="checkbox"/>
442560	WELL	DG	10/14/2015		077-10256	Piceance Fed 28-20E	DG	<input type="checkbox"/>
442562	WELL	DG	11/26/2015		077-10257	Piceance Fed 28-15E	DG	<input type="checkbox"/>
442563	WELL	DG	10/24/2015		077-10258	Piceance Fed 28-18E	DG	<input type="checkbox"/>
442564	WELL	DG	11/07/2015		077-10259	Piceance Fed 28-17E	DG	<input type="checkbox"/>
442565	WELL	DG	12/05/2015		077-10260	Piceance Fed 28-10E	DG	<input type="checkbox"/>
442566	WELL	DG	12/13/2015		077-10261	Piceance Fed 28-07E	DG	<input type="checkbox"/>
442567	WELL	DG	11/12/2015		077-10262	Piceance Fed 28-16E	DG	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>17</u>	Production Pits: _____
Condensate Tanks: <u>8</u>	Water Tanks: _____	Separators: <u>5</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
DRILLING/RECOMP	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	NO
Comment	

Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

Predrill

Location ID: 442547

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Date retrieval failed for the subreport 'Subreport1' located at: \\10.12.100.15\FarmReports\Insp\InspCOA.rdlc. Please check t

S/AR: _____ **Comment:** Notifications have been received.

CA: _____ **Date:** _____

Wildlife BMPs:

Date retrieval failed for the subreport 'Subreport2' located at: \\10.12.100.15\FarmReports\Insp\InspBMP.rdlc. Please check t

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 442547 Type: WELL API Number: 077-10247 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Patterson 306 Pusher/Rig Manager: _____

Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: _____
YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____

Inspector Name: CONKLIN, CURTIS

Multi-Well: YES Disposal Location: Stored on location

Comment:

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

The subreport 'rptInsp13' could not be found at the