

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date: 12/22/2015
Document Number: 682400184
Overall Inspection: SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>439849</u>	<u>439849</u>	<u>Binschus, Chris</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		luke.reddy@anadarko.com	
		rscCOGCCinspections@anadarko.com	

Compliance Summary:

QtrQtr: NESW Sec: 14 Twp: 3N Range: 68W

Inspector Comment:

This is a construction inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
439850	WELL	XX	11/14/2014		123-40575	DOCHEFF 33N-15HZ	CI	<input checked="" type="checkbox"/>
439851	WELL	XX	11/14/2014		123-40576	DOCHEFF 12C-15HZ	CI	<input checked="" type="checkbox"/>
439852	WELL	XX	11/14/2014		123-40577	DOCHEFF 33N-13HZ	CI	<input checked="" type="checkbox"/>
439853	WELL	XX	11/14/2014		123-40578	DOCHEFF 32N-13HZ	CI	<input checked="" type="checkbox"/>
439854	WELL	XX	11/14/2014		123-40579	DOCHEFF 12N-13HZ	CI	<input checked="" type="checkbox"/>
439855	WELL	XX	11/14/2014		123-40580	DOCHEFF 32N-15HZ	CI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>6</u>	Production Pits: _____
Condensate Tanks: <u>1</u>	Water Tanks: <u>3</u>	Separators: <u>14</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: <u>2</u>	Pump Jacks: <u>6</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>0</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 439849

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: SATISFACTORY

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Date retrieval failed for the subreport 'Subreport1' located at: \\10.12.100.15\FarmReports\Insp\InspCOA.rdlc. Please check t

S/AR: SATISFACTORY **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

Date retrieval failed for the subreport 'Subreport2' located at: \\10.12.100.15\FarmReports\Insp\InspBMP.rdlc. Please check t

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 439850 Type: WELL API Number: 123-40575 Status: XX Insp. Status: CI

Facility ID: 439851 Type: WELL API Number: 123-40576 Status: XX Insp. Status: CI

Facility ID: 439852 Type: WELL API Number: 123-40577 Status: XX Insp. Status: CI

Facility ID: 439853 Type: WELL API Number: 123-40578 Status: XX Insp. Status: CI

Facility ID: 439854 Type: WELL API Number: 123-40579 Status: XX Insp. Status: CI

Facility ID: 439855	Type: WELL	API Number: 123-40580	Status: XX	Insp. Status: CI
---------------------	------------	-----------------------	------------	------------------

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

The subreport 'rptInsp13' could not be found at the

COGCC Comments

Comment	User	Date
This is a construction inspection. All stormwater BMPs were installed prior to construction. Topsoil has been segregated and stored.	binschusc	12/24/2015
Refer to attached photos in Doc.#682400185.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682400185	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3748090