

Interim Reclamation Inspection

Inspection Date: 12/22/2015

Operator: Noble Energy Inc.

Location ID: 422926

API #: 05-123-33451

Weld County, CO

NWNW Section 34 T9N R59W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo taken from north end of location. Photo of sign at access road.



Figure 2: Photo of sign at well.



Figure 3: Photo taken from north end of location, facing west. Photo shows interim area.



12.22.2015 13:42

Figure 4: Photo taken from north end of location, facing southwest. Photo shows interim and project area.



Figure 5: Photo taken from the northern end of location, facing south. Photo shows interim and project area.



Figure 6: Photo taken from the northern end of location, facing east. Photo shows interim and project area.



Figure 7: Photo taken from the northwest end of location, facing east. Photo shows interim and project area.



Figure 8: Photo taken from northwest corner of location, facing south. Photo shows interim reclamation in process.



Figure 9: Photo taken from southwest corner of location, facing north. Photo shows interim reclamation in process.



Figure 10: Photo taken from southwest corner of location, facing east. Photo shows interim reclamation in process.



Figure 11: Photo taken from southern end of location, facing west. Photo shows interim reclamation in process, right of fenceline. Photo shows weed debris accumulation in fenceline.



12.22.2015 13:51

Figure 12: Photo taken from southern end of location, facing northeast. Photo shows interim reclamation in process. Photo shows weed debris accumulation in fenceline.



Figure 13: Photo taken from central area of location. Photo of wooden planks stored on interim area.