



photo 1: Facing south along the former access road to the location.



photo 2: Facing south along the former access road towards the location.



photo 3: East side of the location facing west.



photo 4: South side of the location facing northwest.



Photo 5: West side of the location facing east.



Photo 6: Area at the center of the location (~20'x10') with no vegetation establishment.



Photo 7: South side of the location facing north.



Photo 8: Surrounding vegetation, reference area.