

State of Colorado
Oil and Gas Conservation Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax:(303)894-2109

FOR OGCC USE ONLY
REM 9437
Document 2144778
Date 11/25/2015

OGCC Employee:

Spill Complaint
 Inspection NOAV

Tracking No: _____

SITE INVESTIGATION AND REMEDIATION WORKPLAN

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. Form 27 is intended to be used whenever possible. Additional documentation will be required when large volumes of soil and groundwater have been impacted or involve large facilities with multiple source areas. See Rule 910. Attach as many pages as needed to fully describe the proposed work.

CAUSE OF CONDITION BEING INVESTIGATED AND REMEDIATED

Spill or Release Plug & Abandon Central Facility Closure Site/Facility Closure Other (describe): _____

OGCC Operator Number: <u>95960</u>	Contact Name and Telephone: _____
Name of Operator: <u>Wexpro Company</u>	<u>April Stegall</u>
Address: <u>PO Box 458</u>	No: <u>307.352.7561</u>
City: <u>Rock Springs</u> State: <u>WY</u> Zip: <u>82902</u>	Fax: <u>307.352.7583</u>
API Number: <u>05-081-05429</u>	County: <u>Moffat</u>
Facility Name: <u>JA Lee 1 Pit</u>	Facility Number: <u>100381</u>
Well Name: <u>JA Lee</u>	Well Number: <u>1</u>
Location: (QtrQtr, Sec, Twp, Rng, Meridian): <u>NWNE-8-11N-97W</u> Latitude: <u>40.932565</u> Longitude: <u>-108.313024</u>	

TECHNICAL CONDITIONS

Type of Waste Causing Impact (crude oil, condensate, produced water, etc): produced water

Site Conditions: Is location within a sensitive area (according to Rule 901e)? Y N If yes, attach evaluation.

Adjacent land use (cultivated, irrigated, dry land farming, industrial, residential, etc.): Rangeland, Non-cropland

Soil type, if not previously identified on Form 2A or Federal Surface Use Plan: Torriorthents

Potential receptors (water wells within 1/4 mi, surface waters, etc.): 577' from natural drainage

Description of Impact (if previously provided, refer to that form or document):

Impacted Media (check):	Extent of Impact:	How Determined:
<input checked="" type="checkbox"/> Soils	<u>Unknown</u>	_____
<input type="checkbox"/> Vegetation	_____	_____
<input type="checkbox"/> Groundwater	_____	_____
<input checked="" type="checkbox"/> Surface Water	<u>None</u>	<u>Visual</u>

REMEDIATION WORKPLAN

Describe initial action taken (if previously provided, refer to that form or document):

Based on historic imagery, pit was closed prior to 2000.

Describe how source is to be removed:

It is unknown how source was removed. No past analysis or documentation is on record.

Describe how remediation of existing impacts is to be accomplished, including removal and disposal at an injection well or licensed facility, land treatment on site, removal of impacted groundwater, insitu bioremediation, burning of oily vegetation, etc.:

To be determined once soil analysis is received.

FORM 27 Rev 6/99

State of Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
(303)894-2100 Fax:(303)894-2109



Tracking Number: _____
Name of Operator: Wexpro
OGCC Operator No: _____
Received Date: _____
Well Name & No: _____
Facility Name & No: 100381, 312784

Page 2
REMEDIATION WORKPLAN (Cont.)

OGCC Employee: _____

If groundwater has been impacted, describe proposed monitoring plan (# of wells or sample points, sampling schedule, analytical methods, etc.):

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing. Use additional sheet for description if required.

Wexpro intends to obtain a sample of the pit bottom and a sample of the side wall where the load line was present. Offsite samples will also be obtained for analysis. All samples will be tested per Table 910-1. Due to pit being closed, core samples will be obtained using a backhoe, posthole digger or small auger. Original pit was approximately 5 feet deep.

Attach samples and analytical results taken to verify remediation of impacts. Show locations of samples on an onsite schematic or drawing.

Is further site investigation required? Y N If yes, describe:

Final disposition of E&P waste (landtreated and disposed onsite, name of licensed disposal facility, recycling, reuse, etc.):

IMPLEMENTATION SCHEDULE

Date Site Investigation Began: 7/17/2015 Date Site Investigation Completed: TBD Date Remediation Plan Submitted: 11/24/2015
Remediation Start Date: FALL 2016 Anticipated Completion Date: FALL 2016 Actual Completion Date: TBD

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.


Print Name: April Stegall Signed: April Stegall
Title: Reclamation Agent Date: 11/24/2015


OGCC Approved: Kim Wendel Title: EPS Date: 12/31/15

See COA's Attached


- The pit appears to have been closed between 2005-2009 per COGIS aerials
- The vertical and horizontal extent of the pit should be determined through the soil investigation.
- Discrete samples (minimum of 3-5) should be taken from pit wall; with at least one from the true pit bottom. Samples should be taken to adequately characterize any impact from pit.
- Samples should be analyzed for table 910-1.
- Guidance for sample locations should be taken from rule 910.b(3)B
- Final Reclamation should comply with 1000 series rules.
- Request for Closure will NOT be approved without Operator providing notice to Environmental staff Kris Neidel (kris.neidel@state.co.us) or 970-871-1963 72hrs prior to mobilization at begin of work.
- The Lat/Long provided on Form was for wellhead, operator should provided Lat/Long for pit at request for No Further Action.

Soilmap - Territorhunts





Top of water distance



0
750
1500
3000

1" = 1500 Feet

Ace in the Hole

Draw

Powder Wash

577


39
FT

4

JALEE 1
PROPOSED

Legend

- Feature 1
- Untitled Path



JALEE 1

offsite #2

offsite #1

pit wall sample

pit floor sample

offsite #3

