

Final Reclamation Inspection

01/04/2016

Operator: Beren Corporation

Location ID: 317222

API #: 05-121-09791

Washington County, CO

Section 12 T4S R54W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo taken from southeast end of well location, facing west.



Figure 2: Photo taken from southeast end of well location, facing north.



Figure 3: Photo taken from northwest end of well location, facing south.



Figure 4: Photo taken from northwest end of well location, facing east.



Figure 5: Photo of disturbance approximately 20 yards east of well location.



Figure 6: Photo taken from southern end of well location, facing north. Photo shows beginning of vegetation transect.



Figure 7: Photo taken at 50th foot of transect. Photo taken from west side of transect, facing east.



Figure 8: Photo taken at 50th foot of transect. Photo taken from east side of transect, facing west.



Figure 9: Photo taken at 50th foot of transect. Photo of vegetation at 50 feet.



Figure 10: Photo taken from north end of location, facing south. Photo shows transect end point.



Figure 11: Photo taken from west of disturbance area. Photo of reference area, facing north.



Figure 12: Photo taken from west of disturbance area. Photo of reference area, facing east.



Figure 13: Photo taken from west of disturbance area. Photo of reference area, facing south.



Figure 14: Photo taken from west of disturbance area. Photo of reference area, facing west.



Figure 15: Photo taken from west of disturbance area. Photo of starting point for reference area's vegetation transect.



Figure 16: Photo taken at 50th foot of reference transect. Photo taken from east side of transect, facing west.



Figure 17: Photo taken at 50th foot of reference transect. Photo taken from west side of transect, facing east.



Figure 18: Photo taken at 50th foot of reference transect. Photo of vegetation at 50 feet.



Figure 19: Photo shows reference transect end point, facing south.