

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
12/18/2015

Document Number:
673402811

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>421169</u>	<u>413771</u>	<u>Waldron, Emily</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>95960</u>
Name of Operator:	<u>WEXPRO COMPANY</u>
Address:	<u>P O BOX 45003</u>
City:	<u>SALT LAKE CITY</u> State: <u>UT</u> Zip: <u>84145-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Freeman, Sarah		sarah.freeman@state.co.us	
Fredrickson, Tammy	307-352-7566	Tammy.Fredrickson@questar.com	

Compliance Summary:

QtrQtr: NESW Sec: 33 Twp: 12N Range: 97W

Inspector Comment:

APD expired 11/27/2012. No form 4 to abandon permit received. No new permit received.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
421169	WELL	XX	11/27/2012	LO	081-07642	Carl Allen 38	XX	<input checked="" type="checkbox"/>
421170	WELL	XX	11/27/2012	LO	081-07643	Carl Allen 39	XX	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: <u>1</u>	Drilling Pits: <u>1</u>	Wells: <u>2</u>	Production Pits: <u> </u>
Condensate Tanks: <u>2</u>	Water Tanks: <u>1</u>	Separators: <u>2</u>	Electric Motors: <u> </u>
Gas or Diesel Mortors: <u> </u>	Cavity Pumps: <u> </u>	LACT Unit: <u> </u>	Pump Jacks: <u> </u>
Electric Generators: <u> </u>	Gas Pipeline: <u>1</u>	Oil Pipeline: <u> </u>	Water Pipeline: <u> </u>
Gas Compressors: <u> </u>	VOC Combustor: <u>1</u>	Oil Tanks: <u> </u>	Dehydrator Units: <u>2</u>
Multi-Well Pits: <u> </u>	Pigging Station: <u> </u>	Flare: <u> </u>	Fuel Tanks: <u> </u>

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

OGLA	kubeczkod	Location is in a sensitive area because of proximity to surface water; therefore, operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations; including, but not limited to, construction of a berm or diversion dike, diversion/collection trenches within and/or outside of berms/dikes, site grading, or other comparable measures (i.e., best management practices (BMPs) associated with stormwater management) sufficiently protective of nearby surface water. Any berm constructed at the well pad location will be stabilized, inspected at regular intervals (at least every 14 days), and maintained in good condition.	01/01/2011
OGLA	kubeczkod	Operator must implement best management practices to contain any unintentional release of fluids, including any fluids conveyed via temporary surface pipelines.	01/01/2011

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 421169 Type: WELL API Number: 081-07642 Status: XX Insp. Status: XX

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: RANGELAND
Comment: _____

1003a. Debris removed? _____ CM _____ CA _____ CA Date _____
Waste Material Onsite? _____ CM _____ CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____ CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____ CA _____ CA Date _____
Guy line anchors removed? _____ CM _____ CA _____ CA Date _____
Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland
Top soil replaced _____ Recontoured _____ Perennial forage re-established _____
Non-Cropland
Top soil replaced _____ Recontoured _____ 80% Revegetation _____

Inspector Name: Waldron, Emily

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Pass _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
APD expired 11/27/2012. No form 4 to abandon permit received. No new permit received.	waldrone	01/07/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673402812	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3756244