

Interim Reclamation Inspection

1/6/2016

Operator: Bonanza Creek Operating

Location ID: 428205

API: 05-123-35276

Weld County, CO

Section 15 T5N R61W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo of sign at well.



Figure 2: Photo taken at well. Photo shows stained soil and small leak.



Figure 3: Photo taken from northeast end of location, facing west. Photo of interim area.



Figure 4: Photo taken from northeast end of location, facing south. Photo of interim area.



Figure 5: Photo taken from southeast end of location, facing north. Photo of interim area.



Figure 6: Photo taken from southeast end of location, facing west. Photo of interim area.



Figure 7: Photo of sign at battery.



Figure 8: Photo taken from southwest end of location, facing east. Photo of interim area.



Figure 9: Photo taken from southwest end of location, facing north. Photo of interim area.



Figure 10: Photo taken from northwest end of location, facing south. Photo of interim area.



Figure 11: Photo taken from northwest end of location, facing east. Photo of interim area.