



photo 1: Facing south along access road toward the location. Note: Vegetation has not established.




photo 2: North side of the location facing south toward the location.



Photo 3: Center of the location facing north.



Photo 4: Center of the location facing west.



Photo 5: Center of the location facing south.



Photo 6: Center of the location facing east.



Photo 7: Area with no vegetation establishment approx. 100ft. x 60 ft.



Photo 8: A dirt pile was noticed at the east side of the location which has not been recontoured.



Photo 9: Weed growth (kochia) was noticed throughout the location.



Photo 10: Surrounding undisturbed vegetation outside of the location.