

Abandoned Location Inspection



Photo 1. Photo taken of PR well 123-21181, confirming the AL status of 123-30991. It appears 123-30991 was never built at location. This is a well release on an active location.

Abandoned Location Inspection



Photo 2. Photo taken of PR well 123-21181, facing West confirming the AL status of 123-30991. It appears 123-30991 was never built at location. This is a well release on an active location.