

Abandoned Location Inspection



Photo 1. Photo taken of PR well 001-09584, confirming the AL status of 001-09726. It appears 001-09726 was never built at location. This is a well release on an active location.

Abandoned Location Inspection



Photo 2. Photo taken of PR well 001-09094, confirming the AL status of 001-09726. It appears 001-09726 was never built at location. This is a well release on an active location.