

Abandoned Location Inspection



Photo 1. Photo taken of PR well 123-19113, confirming the AL status of 123-32529 and the expired APDs 123-32523, 123-32525, and 123-32528. It appears 123-32529, 123-32523, 123-32525, and 123-32528 were never built at location. This is a well release on an active location.

Abandoned Location Inspection



Photo 2. Photo taken of PR well 123-19113, confirming the AL status of 123-32529 and the expired APDs 123-32523, 123-32525, and 123-32528. It appears 123-32529, 123-32523, 123-32525, and 123-32528 were never built at location. This is a well release on an active location.