

Construction Inspection



Photo 1. Photo taken from the entrance of location, facing East.

Construction Inspection



Photo 2. Photo taken from southwest location, facing North. Stormwater and sediment control BMPs installed along perimeter of location.

Construction Inspection



Photo 3. Photo taken from northern location, facing West. Stormwater and sediment control BMPs installed along perimeter of location. CDOT recommends that berms be properly compacted with no breaks in the berm. Operator said that perimeter berms will be compacted once favorable conditions are permitted.

Construction Inspection



Photo 4. Photo taken from northern location, facing East. Topsoil stockpile in center of photo.

Construction Inspection



Photo 5. Photo taken from eastern location, facing West. Stormwater and sediment control BMPs installed along perimeter of location. CDOT recommends that berms be properly compacted with no breaks in the berm. Operator said that perimeter berms will be compacted once favorable conditions are permitted.

Construction Inspection



Photo 6. Photo taken from southeast location, facing West. Stormwater and sediment control BMPs installed along perimeter of location. CDOT recommends that berms be properly compacted with no breaks in the berm. Operator said that perimeter berms will be compacted once favorable conditions are permitted.

Construction Inspection



Photo 7. Photo taken from southern location, facing East. Stormwater and sediment control BMPs installed along perimeter of location. CDOT recommends that berms be properly compacted with no breaks in the berm. Operator said that perimeter berms will be compacted once favorable conditions are permitted.

Construction Inspection



Photo 8. Photo taken from southern location, facing West. Stormwater and sediment control BMPs installed along perimeter of location. CDOT recommends that berms be properly compacted with no breaks in the berm. Operator said that perimeter berms will be compacted once favorable conditions are permitted.