

Facility: 117729
Facility: 117730
Location: 317129
Well: 121-09121



LEASE INSPECTION FORM

Date 5-29-84
Operator Mikston Petro. Field Pinto
Lease Name & No. Theurer farms #22-28 County Washington
Tank Battery No. 3N 52 E 28 Location Sec NW 28-3N-52W
Legal Description

Type of Inspection _____
Water Inflow 110 (Bbls. per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)
Type of Tank

SKIM TANK 7' Dia Con S.T., 10x20 Wood CVD
100% oil CVD Water Flowing

PIT No. 1 30'x60' Not CVD, 75% oil CVD

PIT NO. 2 _____

PIT NO. 3 _____

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

Pits Not Lined

RECOMMENDED ACTION (If Required) Remove oil

INSPECTOR James