

Interim Reclamation Inspection

2/17/2016

Operator: Atlas Resources

Location ID: 314130

API: 095-06222

Phillips County, CO

NENE Section 6 T8N R43W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo of sign at well.



Figure 2: Photo taken from well head. Photo of white container. Container is either improperly stored or trash debris.



Figure 3: Photo taken from the northwest end of location, facing east. Photo shows vegetation on interim area.



Figure 4: Photo taken from the northwest end of location, facing south. Photo shows vegetation on interim area.



Figure 5: Photo taken from the southwest end of location, facing north. Photo shows vegetation on interim area.



Figure 6: Photo taken from the southwest end of location, facing east. Photo shows vegetation on interim area.



Figure 7: Photo taken from the southeast end of location, facing west. Photo shows vegetation on interim area.



Figure 8: Photo taken from the south east end of location, facing north. Photo shows vegetation on interim area.



Figure 9: Photo taken from the northeast end of location, facing south. Photo shows vegetation on interim area.



Figure 10: Photo taken from the northeast end of location, facing west. Photo shows vegetation on interim area.