

Interim Reclamation Inspection

2/17/2016

Operator: Atlas Resources

Location ID: 420894

API: 095-06299

Phillips County, CO

SESW Section 31 T9N R43W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo of sign at well.



Figure 2: Photo taken from the location, facing west. Photo shows pump and well.



Figure 3: Photo taken from the southwest corner of location, facing north. Photo shows vegetation on interim area, and project area.



Figure 4: Photo taken from the southwest corner of location, facing east. Photo shows vegetation on interim area, and project area.



Figure 5: Photo taken from the southeast corner of location, facing west. Photo shows vegetation on interim area, and project area.



Figure 6: Photo taken from the southeast corner of location, facing north. Photo shows vegetation on interim area, and project area.



Figure 7: Photo taken from the northeast corner of location, facing south. Photo shows vegetation on interim area, and project area.



Figure 8: Photo taken from the northeast corner of location, facing west. Photo shows vegetation on interim area, and project area.



Figure 9: Photo taken from the access road north of location, facing south. Photo shows project area.