



Photo 1. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is comprised of seeded species such as smooth brome (*Bromus inermis*) and intermediate wheatgrass (*Thinopyron intermedium*) as well as weedy kochia (*Kochia scoparia*) and cheatgrass (*Bromus tectorum*).



Photo 2. Area in western portion of the interim reclamation area where vegetation has been damaged from what appears to be recent workover activities.



Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 4. View of the southern portion of the interim reclamation area from the southwestern corner facing eastward. Portions of interim reclamation area where vegetation has been damaged will need revegetation.