

Plugged and Abandoned Inspection



Photo 1. Photo taken from center of location, facing West. Location has been reclaimed to the private landowner's preference (i.e., horse pasture).

Plugged and Abandoned Inspection



Photo 2. Photo taken from center of location, facing North. Location has been reclaimed to the private landowner's preference (i.e., horse pasture).

Plugged and Abandoned Inspection



Photo 3. Photo taken from center of location, facing East. Location has been reclaimed to the private landowner's preference (i.e., horse pasture).

Plugged and Abandoned Inspection



Photo 4. Photo taken from center of location, facing South. Location has been reclaimed to the private landowner's preference (i.e., horse pasture).

Plugged and Abandoned Inspection



Photo 5. Photo taken from south of location, facing North. Location has been marked with a pole in center of photo.