

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
02/29/2016
Document Number:
685300075
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>215523</u>	<u>333513</u>	<u>St John, William (Cal)</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10000</u>
Name of Operator:	<u>BP AMERICA PRODUCTION COMPANY</u>
Address:	<u>380 AIRPORT RD</u>
City:	<u>DURANGO</u> State: <u>CO</u> Zip: <u>81303</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Compliance Summary:

QtrQtr: NESE Sec: 8 Twp: 33N Range: 9W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/14/2012	661700184	PR	PR	SATISFACTORY	P		No
03/28/2011	200305650	PR	PR	SATISFACTORY			No
07/08/2009	200214231	ES	PR	ACTION REQUIRED			No
06/25/2008	200191497	PR	PR	SATISFACTORY			No
04/29/2008	200189074	PR	PR	SATISFACTORY			No
07/25/2007	200120668	PR	PR	SATISFACTORY			No
07/24/2007	200120667	PR	PR	SATISFACTORY			No
03/07/2006	200088524	PR	PR	SATISFACTORY		Pass	No
10/21/2004	200065566	PR	PR	SATISFACTORY		Pass	No
04/08/2003	200037997	PR	PR	SATISFACTORY		Pass	No
09/14/2001	200021620	PR	PR	SATISFACTORY		Pass	No
09/27/2000	200010369	PR	PR	SATISFACTORY		Pass	No
03/06/1998	500149176	PR	PR			Pass	No
04/05/1996	500149175	BH	PR			Pass	No
02/15/1996	500149174	PR	PR				No
05/02/1995	500149173	PR	PR			Pass	No
05/01/1995	500149172	BH	PR			Pass	No
10/21/1994	500149171	PR	PR			Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
214153	WELL	PR	10/30/1960	GW	067-05470	BONDAD 33-9 32	PR	<input type="checkbox"/>
215523	WELL	PR	04/04/2007	GW	067-07128	ORAN W SHORT A 1	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____
 Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____
 Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____
 Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	Location Sign		
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK BATTERY	SATISFACTORY	Panel		
WELLHEAD	SATISFACTORY	Panel		
SEPARATOR	SATISFACTORY	Panel		

OTHER	SATISFACTORY	Panels around Telemetry Equipment.		
-------	--------------	------------------------------------	--	--

Equipment:				
Type: Bird Protectors	# 1	Satisfactory/Action Required:		SATISFACTORY
Comment				
Corrective Action				Date:
Type: Flow Line	# 1	Satisfactory/Action Required:		SATISFACTORY
Comment				
Corrective Action				Date:
Type: Ancillary equipment	# 1	Satisfactory/Action Required:		SATISFACTORY
Comment Telemetry Equipment				
Corrective Action				Date:
Type: Vertical Heated Separator	# 1	Satisfactory/Action Required:		SATISFACTORY
Comment				
Corrective Action				Date:
Type: Gas Meter Run	# 1	Satisfactory/Action Required:		SATISFACTORY
Comment				
Corrective Action				Date:
Type: Ancillary equipment	# 1	Satisfactory/Action Required:		SATISFACTORY
Comment Wellhead				
Corrective Action				Date:

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL	,
S/AR	SATISFACTORY	Comment:		
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	95 BBLs
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	NO
Comment	

Flaring:

Type	Satisfactory/Action Required	
Comment:		
Corrective Action:	Correct Action	Date:

Predrill

Location ID: 215523

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:**

CA: **Date:** _____

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 215523 Type: WELL API Number: 067-07128 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____
 CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? _____
 CM _____
 CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____
 CM _____
 CA _____ CA Date _____

Guy line anchors marked? _____
 CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION
Cropland

Inspector Name: St John, William (Cal)

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT