



Photo#1: Over View of Location looking to East. Arrow shows P&A Marker. Portion of site back of Red Arc are Areas no Longer Needed for Use.



Photo#2: View of Location to NW





Photo#3: Associated Facility that needs removed.



Photo#4: Vehicle Incursion into Interim Vegetation at SE Corner of Pad