

J P Weise 2

Inspection# 673403050

Spill at pump jack.



Breach/rill in land farm berm.



Breach/rill in land farm berm.



Drainage on east side of location.

