



Photo#1: View over Location to NE



Photo#2: View over Location to NW.

March 6, 2016

Inspection Photos Encana P&A 077-09060





Photo#3: Emerging Vegetation at Location.